



AutoPilot® 3 Release Notes

Known issues in software version 3.0.313:

- AutoPilot will not connect to ARC-16 sites if the software is configured to answer after 8 rings or more. Set the number of rings to 7 or fewer.
- When printing a report, the Windows print dialog shows an erroneous page length of 65,535.
- When upgrading from AutoPilot 2 to AutoPilot 3, the AP2 desktop icon is not updated.
- Site data is logged according to the name of the site. If the site name changes, new reports will only include data logged after the name change.
- The AutoPilot active alarms window show all out of tolerance conditions, even if the ARC-16 unit's limits monitoring function is disabled.
- In rare cases, docking a window may cause the window to disappear. If this happens, deleting the toolbar file resolves the issue.
- When using the option to disable command buttons while the raise or lower relay is active, button focus is sometimes directed to the wrong button after a command is issued.
- The option to send email alerts using secure password authentication actually refers to password encryption.
- The option to purge logged data from the database does not always reduce the file size.
- When the background color of an angular meter is mapped to a status condition, the background color does not always show the correct status data.
- In a multi-site system, the connection status is not always updated immediately for child sites (units that rely on a parent unit for connection to the PC).