



GSC3000/VRC2500 COM Port Settings Correction

Depending on the serial number and firmware version of your GSC3000 or VRC2500, the COM port settings specified in the installation and operation manual may be incorrect. The following serial numbers and firmware combinations are affected:

- GSC3000 I/O 16s with s/n 031001 or later *and* running firmware 5.1.14 or later
- VRC2500s with s/n 032301 or later *and* running firmware 5.1.14 or later
- GSC3000 I/O 8s with s/n 071001 or later *and* running firmware 5.1.14 or later

If your unit meets the criteria above, please use the following COM port settings when connecting a PC, full-time modem or dial up modem:

PC (null modem cable)

VRC2500	DIRECT
GSC3000	COM 2

Full-Time Modems

VRC2500	DIRECT
GSC3000	COM 2

Dial-Up Modems

GSC3000	COM 1
VRC2500	FULL-TIME