



## Release Notes

### Plus-X Dual IP-8 Adapter firmware version 1.0.10

#### Scope

This document describes the changes in Plus-X Dual IP-8 Adapter firmware from version 1.0.5 to version 1.0.10.

#### *Changes from version 1.0.7 to version 1.0.10*

##### New Features and Enhancements

##### **The Burk Firmware Loader is now supported:**

Following installation of firmware version 1.0.10, subsequent firmware upgrades will utilize the Burk Firmware Loader, providing enhanced upload reliability.

##### Resolved Issues

##### **Meter readings are now maintained without fluctuation when the Maintenance Mode button is pressed:**

Pressing the Maintenance Mode button on the front panel of the Plus-X Dual IP-8 Adapter now has no effect on reported meter values.

#### *Changes from version 1.0.5 to version 1.0.7*

##### Resolved Issues

##### **New MAC address range is now supported:**

A new range of MAC addresses has been accommodated for production of Plus-X Dual IP-8 Adapters. This change has no user impact.