



## Product Update

### ***Firmware version 5.1.1.1 is now available for ARC Plus Touch and ARC Plus SL***

---

ARC Plus Touch and ARC Plus SL systems running version 5 firmware can now be upgraded with firmware version 5.1.1.1. Changes from firmware version 5.1.0.4 to 5.1.1.1 are highlighted below. Detailed descriptions of these changes can be found in the Release Notes document included in the firmware download package. This version of ARC Plus firmware requires the use of AutoLoad Plus version 3.2.7 or higher and AutoPilot® version 4.3.58 or higher.

#### **Resolved Issues**

- The number of simultaneous TCP/IP connections has been increased.
- Support for unencrypted connections has been restored.

To install the new firmware, follow these steps:

- 1) Visit [www.burk.com/downloads](http://www.burk.com/downloads) and select the support page for ARC Plus Touch or ARC Plus SL.
- 2) Download and install Burk Firmware Loader 1.1.1 or higher.
- 3) Download Manual – Burk Firmware Loader and follow the instructions for updating the ARC Plus firmware.

For further information or for assistance with this upgrade, please contact Burk technical support at 978-486-3711 or by email at [support@burk.com](mailto:support@burk.com).