



## Product Update

*Firmware version 1.0.18 is now available for Plus-X 300*

---

Plus-X 300 units can now be upgraded with firmware version 1.0.18. Changes from firmware version 1.0.16 to 1.0.18 are highlighted below. Detailed descriptions of these changes can be found in the Release Notes document included in the firmware download package.

### Resolved Issues

- Plus-X device handshake has been enhanced.

To install the new firmware, visit [www.burk.com/downloads](http://www.burk.com/downloads), select the Burk Firmware Loader support page and download "Manual - Burk Firmware Loader Manual Rev A". Follow these instructions to upgrade your system to firmware.

For further information or for assistance with this upgrade, please contact Burk technical support at 978-486-3711 or by email at [support@burk.com](mailto:support@burk.com).