



Product Update

Firmware version 1.0.16 is now available for Plus-X 600

Plus-X 600 units can now be upgraded with firmware version 1.0.16. Changes from firmware version 1.0.15 to 1.0.16 are highlighted below. Detailed descriptions of these changes can be found in the Release Notes document included in the firmware download package.

Resolved Issues

- The Plus-X 600 now restores communication immediately after re-initialization.

Refer to Technical Bulletin *Updating Firmware in the Plus-X 600* for firmware upload instructions.

For further information or for assistance with this upgrade, please contact Burk technical support at 978-486-3711 or by email at support@burk.com.