



## Product Update

### ***Firmware version 1.0.20 is now available for Plus-X AC-8***

---

Plus-X AC-8 units can now be upgraded with firmware version 1.0.20. Changes from firmware version 1.0.18 to 1.0.20 are highlighted below. Detailed descriptions of these changes can be found in the Release Notes document included in the firmware download package.

#### **New Features and Enhancements**

- Re-establishing ARC Plus communication is now optional.
- Password selection for the administrator account is now required.

#### **Resolved Issues**

- Link LED properly indicates the ARC Plus connection status.
- Mapping AC outlet status is no longer required.
- Successfully issued commands no longer produce an error.

To install the new firmware, visit [www.burk.com/downloads](http://www.burk.com/downloads), select the Burk Firmware Loader support page and download "Manual - Burk Firmware Loader Manual Rev A". Follow these instructions to upgrade your system to the latest firmware.

For further information or for assistance with this upgrade, please contact Burk technical support at 978-486-3711 or by email at [support@burk.com](mailto:support@burk.com).