



Product Update

Firmware version 1.0.12 is now available for Plus-X Dual IP-8 Adapter

Plus-X Dual IP-8 Adapters can now be upgraded with firmware version 1.0.12. Changes from firmware version 1.0.11 to 1.0.12 are highlighted below. Detailed descriptions of these changes can be found in the Release Notes document included in the firmware download package.

Resolved Issues

- Maintenance mode is now disabled after a firmware update.

Refer to Technical Bulletin *Updating Firmware in the Plus-X Dual IP-8 Adapter* for firmware upload instructions.

For further information or for assistance with this upgrade, please contact Burk technical support at 978-486-3711 or by email at support@burk.com.