



Product Update

Firmware version 1.0.14 is now available for Plus-X Dual IP-8 Adapter

Plus-X Dual IP-8 Adapters can now be upgraded with firmware version 1.0.14. Changes from firmware version 1.0.13 to 1.0.14 are highlighted below. Detailed descriptions of these changes can be found in the Release Notes document included in the firmware download package.

Caution: Plus-X Dual IP-8 adapters with serial number BR191201 or higher will not operate properly with firmware earlier than 1.0.14.

Resolved Issues

- Voltage readings on meter channels update properly.
- State changes on status channels update properly.

Refer to Burk Firmware Loader Manual for Plus-X Dual IP-8 Adapter firmware upload instructions at <http://www.burk.com/downloads>.

For further information or for assistance with this upgrade, please contact Burk technical support at 978-486-3711 or by email at support@burk.com.