



## Product Update

### ***Firmware version 1.0.5 is now available for PlusConnect™ Nautel GV***

---

PlusConnect Nautel GV units can now be upgraded with firmware version 1.0.5. Changes from firmware version 1.0.1 to 1.0.5 are highlighted below. Detailed descriptions of these changes can be found in the Release Notes document included in the firmware download package.

#### Changes from firmware version 1.0.4 to version 1.0.5

##### New Features and Enhancements

- PlusConnect device handshake has been enhanced.

#### Changes from firmware version 1.0.1 to version 1.0.4

##### New Features and Enhancements

- Loss of communication with the transmitter now results in an ARC Plus system alarm.

##### Resolved Issues

- Unauthorized SNMP communications are now ignored.
- The PlusConnect Nautel GV now automatically re-initializes after loss of communication with the ARC Plus.
- New MAC address range is now supported.
- SNMP packet encoding is now compatible with current-revision Nautel firmware.

To install the new firmware, follow these steps:

- 1) Visit [www.burk.com/downloads](http://www.burk.com/downloads) and select the support page for PlusConnect.
- 2) Download the firmware package for your PlusConnect™.
- 3) Download user instructions for your PlusConnect™ – Follow the instructions for updating firmware defined in the manual.

For further information or for assistance with this upgrade, please contact Burk technical support at 978-486-3711 or by email at [support@burk.com](mailto:support@burk.com).