



Release Notes

Plus-X IIU firmware version 1.1.3

Scope

This document describes the changes in Plus-X IIU firmware from version 1.1.0 to version 1.1.3.

Changes from firmware version 1.1.2 to version 1.1.3

New Features and Enhancements

DHCP is now the default method for initial IP address assignment:

On first power-up after firmware installation or reset to factory default settings, the Plus-X IIU now uses DHCP to obtain an initial IP address. The default hostname PLUSXIIU can be used to connect to the unit. In networks that do not support DHCP the unit self-assigns an initial IP address 192.168.0.100.

Password selection for the administrator account is now required:

On first power-up after firmware installation or reset to factory default settings, the Plus-X IIU now requires the user to specify a password for the administrator account. The password cannot consist of the word "password" in any combination of upper and lower case.

Changes from firmware version 1.1.1 to version 1.1.2

Resolved Issues

The Plus-X IIU now automatically re-initializes after loss of communication with the ARC Plus:

If the communications link between the Plus-X IIU and the controlling ARC Plus system is broken for 3 minutes or more, the Plus-X IIU now automatically re-initializes to ensure proper operation on restoral of communication. Re-initialization has no effect on system configuration.

Changes from firmware version 1.1.0 to version 1.1.1

Resolved Issues

New MAC address range is now supported:

A new range of MAC addresses has been accommodated for production of Plus-X IIU units. This change has no user impact.