



Release Notes

PlusConnect BDI-DPS100 firmware version 1.0.13

Scope

This document describes the changes in PlusConnect BDI DPS-100 firmware from version 1.0.12 to version 1.0.13.

Changes from firmware version 1.0.12 to version 1.0.13

New Features and Enhancements

PlusConnect device handshake has been enhanced:

The PlusConnect BDI-DPS100 now completes a handshake process to confirm receipt of commands sent from the ARC Plus Touch. The ARC Plus enters an error in the event log if a command is not confirmed. This feature requires the use of ARC Plus firmware 5.0.14.1 or higher.

Changes from firmware version 1.0.11 to version 1.0.12

Resolved Issues

The PlusConnect BDI-DPS100 now automatically re-initializes after loss of communication with the ARC Plus:

If the communications link between the PlusConnect and the controlling ARC Plus system is broken for 3 minutes or more, the PlusConnect now automatically re-initializes to ensure proper operation on restoration of communication. Re-initialization has no effect on system configuration.

Changes from firmware version 1.0.10 to version 1.0.11

Resolved Issues

New MAC address range is now supported:

A new range of MAC addresses has been accommodated for production of PlusConnect BDI-DPS100 units. This change has no user impact.