



# Release Notes

## PlusConnect™ GatesAir ZXB firmware version 1.0.12

### Scope

This document describes the changes in PlusConnect GatesAir ZXB firmware from version 1.0.10 to version 1.0.12.

### Changes from firmware version 1.0.10 to version 1.0.12

#### New Features and Enhancements

**PlusConnect device handshake has been enhanced:**

The PlusConnect GatesAir ZXB now completes a handshake process to confirm receipt of commands sent from the ARC Plus Touch. The ARC Plus enters an error in the event log if a command is not confirmed. This feature requires the use of ARC Plus firmware 5.0.14.1 or higher.

**Caution:** Do not install firmware version 1.0.12 if the serial number on your PlusConnect unit is lower than BN100101. Please contact Burk Technology technical support at 978-486-3711 for special instructions.

### Changes from firmware version 1.0.9 to version 1.0.10

#### Resolved Issues

**New MAC address range is now supported:**

A new range of MAC addresses has been accommodated for production of PlusConnect GatesAir ZXB units. This change has no user impact.

**The PlusConnect GatesAir ZXB now automatically re-initializes after loss of communication with the ARC Plus:**

If the communications link between the PlusConnect and the controlling ARC Plus system is broken for 3 minutes or more, the PlusConnect now automatically re-initializes to ensure proper operation on restoration of communication. Re-initialization has no effect on system configuration.