

Release Notes

PlusConnect GatesAir 3DX firmware version 1.0.13

Scope

This document describes the changes in PlusConnect GatesAir 3DX firmware from version 1.0.11 to version 1.0.13.

Changes from firmware version 1.0.11 to version 1.0.13

New Features and Enhancements

PlusConnect device handshake has been enhanced:

The PlusConnect GatesAir 3DX now completes a handshake process to confirm receipt of commands sent from the ARC Plus Touch. The ARC Plus enters an error in the event log if a command is not confirmed. This feature requires the use of ARC Plus firmware 5.0.14.1 or higher.

Caution: Do not install firmware version 1.0.13 if the serial number on your PlusConnect unit is lower than BN100101. Please contact Burk Technology technical support at 978-486-3711 for special instructions.