

Release Notes

PlusConnect GatesAir Z firmware version 1.13

Scope

This document describes the changes in PlusConnect GatesAir Z firmware from version 1.12 to version 1.13.

Changes from firmware version 1.12 to version 1.13

New Features and Enhancements

PlusConnect device handshake has been enhanced:

The PlusConnect GatesAir Z now completes a handshake process to confirm receipt of commands sent from the ARC Plus Touch. The ARC Plus enters an error in the event log if a command is not confirmed. This feature requires the use of ARC Plus firmware 5.0.14.1 or higher.

Caution: Do not install firmware version 1.13 if the serial number on your PlusConnect unit is lower than BN100101. Please contact Burk Technology technical support at 978-486-3711 for special instructions.

Resolved Issues

The power light no longer toggles on and off:

The power LED will now stay on when the unit has power and will not toggle when the unit receives an ARP request.

Changes from firmware version 1.9 to version 1.12

Resolved Issues

The PlusConnect GatesAir Z now automatically re-initializes after loss of communication with the ARC Plus:

If the communications link between the PlusConnect and the controlling ARC Plus system is broken for 3 minutes or more, the PlusConnect now automatically re-initializes to ensure proper operation on restoration of communication. Re-initialization has no effect on system configuration.