



Release Notes

PlusConnect Nautel NX firmware version 1.0.4

Scope

This document describes the changes in PlusConnect Nautel NX firmware from version 1.0.2 to version 1.0.4.

Changes from firmware version 1.0.3 to version 1.0.4

Resolved Issues

The PlusConnect Nautel NX now automatically re-initializes after loss of communication with the ARC Plus:

If the communications link between the PlusConnect and the controlling ARC Plus system is broken for 3 minutes or more, the PlusConnect now automatically re-initializes to ensure proper operation on restoration of communication. Re-initialization has no effect on system configuration.

Changes from firmware version 1.0.2 to version 1.0.3

Resolved Issues

New MAC address range is now supported:

A new range of MAC addresses has been accommodated for production of PlusConnect Nautel NX units. This change has no user impact.