



# Release Notes

## PlusConnect™ Nautel NVLT firmware version 1.0.7

### Scope

This document describes the changes in PlusConnect Nautel NVLT firmware from version 1.0.6 to version 1.0.7.

### *Changes from version 1.0.6 to version 1.0.7*

#### New Features and Enhancements

**PlusConnect device handshake has been enhanced:**

The PlusConnect Nautel NVLT now completes a handshake process to confirm receipt of commands sent from the ARC Plus Touch. The ARC Plus enters an error in the event log if a command is not confirmed. This feature requires the use of ARC Plus firmware 5.0.14.1 or higher

### *Changes from version 1.0.5 to version 1.0.6*

#### New Features and Enhancements

**Loss of communication with the transmitter now results in an ARC Plus system alarm:**

When SNMP communication is lost between the PlusConnect Nautel NVLT and the transmitter, the controlling ARC Plus unit now issues a system alarm.

#### Resolved Issues

**Unauthorized SNMP communications are now ignored:**

The PlusConnect Nautel NVLT now rejects unauthorized SNMP Get Requests without interrupting the desired SNMP communication with the NVLT transmitter.

### *Changes from version 1.0.4 to version 1.0.5*

#### Resolved Issues

**New MAC address range is now supported:**

A new range of MAC addresses has been accommodated for production of PlusConnect Nautel NVLT units. This change has no user impact.

**The PlusConnect Nautel NVLT now automatically re-initializes after loss of communication with the ARC Plus:**

If the communications link between the PlusConnect and the controlling ARC Plus system is broken for 3 minutes or more, the PlusConnect now automatically re-initializes to ensure proper operation on restoral of communication. Re-initialization has no effect on system configuration.