



# Release Notes

## PlusConnect Nautel NV firmware version 1.0.11

### Scope

This document describes the changes in PlusConnect Nautel NV firmware from version 1.0.8 to version 1.0.11.

### Changes from firmware version 1.0.10 to version 1.0.11

#### Resolved Issues

**The PlusConnect Nautel GV now rejects communications from unauthorized SNMP devices or managers:**

Unexpected communications from SNMP devices or managers are now ignored by the PlusConnect, ensuring consistent communications with authorized devices.

### Changes from firmware version 1.0.9 to version 1.0.10

#### Resolved Issues

**The PlusConnect Nautel NV now automatically re-initializes after loss of communication with the ARC Plus:**

If the communications link between the PlusConnect and the controlling ARC Plus system is broken for 3 minutes or more, the PlusConnect now automatically re-initializes to ensure proper operation on restoration of communication. Re-initialization has no effect on system configuration.

**The correct Exciter PA Temperature scale factor is now automatically applied:**

The Exciter PA Temperature retrieved from the Nautel NV transmitter is now displayed correctly without need for manual entry of an additional scale factor.

### Changes from firmware version 1.0.8 to version 1.0.9

#### Resolved Issues

**New MAC address range is now supported:**

A new range of MAC addresses has been accommodated for production of PlusConnect Nautel NV units. This change has no user impact.