



# Release Notes

## PlusConnect Nautel VS firmware version 1.0.8

### Scope

This document describes the changes in PlusConnect Nautel VS firmware from version 1.0.5 to version 1.0.8.

### Changes from firmware version 1.0.7 to version 1.0.8

#### Resolved Issues

**The PlusConnect Nautel VS now properly ignores unauthorized SNMP access attempts:**

An attempt by an SNMP manager to interrogate the PlusConnect Nautel VS is now ignored, causing the unauthorized communication to fail.

### Changes from firmware version 1.0.6 to version 1.0.7

#### Resolved Issues

**The PlusConnect Nautel VS now automatically re-initializes after loss of communication with the ARC Plus:**

If the communications link between the PlusConnect and the controlling ARC Plus system is broken for 3 minutes or more, the PlusConnect now automatically re-initializes to ensure proper operation on restoration of communication. Re-initialization has no effect on system configuration.

### Changes from firmware version 1.0.5 to version 1.0.6

#### Resolved Issues

**New MAC address range is now supported:**

A new range of MAC addresses has been accommodated for production of PlusConnect Nautel VS units. This change has no user impact.