

Release Notes

PlusConnect Nautel V firmware version 1.0.2

Scope

This document describes the changes in PlusConnect Nautel V firmware from version 1.0.1 to version 1.0.2.

Resolved Issues

The PlusConnect Nautel V now automatically re-initializes after loss of communication with the ARC Plus:

If the communications link between the PlusConnect and the controlling ARC Plus system is broken for 3 minutes or more, the PlusConnect now automatically re-initializes to ensure proper operation on restoral of communication. Re-initialization has no effect on system configuration.

New MAC address range is now supported:

A new range of MAC addresses has been accommodated for production of PlusConnect Nautel V units. This change has no user impact.