Release Notes

Plus-X RP-8 Adapter firmware version 1.0.4

Scope

This document describes the changes in Plus-X RP-8 Adapter firmware from version 1.0.3 to version 1.0.4.

Resolved Issues

New MAC address range is now supported:

A new range of MAC addresses has been accommodated for production of Plus-X RP-8 Adapters. This change has no user impact.