



Release Notes

PlusConnect™ GatesAir HPX firmware version 1.0.5

Scope

This document describes the changes in PlusConnect GatesAir HPX firmware from version 1.0.3 to version 1.0.5.

Changes from version 1.0.4 to version 1.0.5

New Features and Enhancements

Loss of communication with the transmitter now results in an ARC Plus system alarm:

When SNMP communication is lost between the PlusConnect GatesAir HPX and the transmitter, the controlling ARC Plus unit now issues a system alarm.

Resolved Issues

Unauthorized SNMP communications are now ignored:

The PlusConnect GatesAir HPX now rejects unauthorized SNMP Get Requests without interrupting the desired SNMP communication with the HPX transmitter.

Changes from version 1.0.3 to version 1.0.4

Resolved Issues

New MAC address range is now supported:

A new range of MAC addresses has been accommodated for production of PlusConnect GatesAir HPX units. This change has no user impact.