



## Release Notes

### PlusConnect™ GatesAir ZXB firmware version 1.0.10

#### Scope

This document describes the changes in PlusConnect GatesAir ZXB firmware from version 1.0.9 to version 1.0.10.

#### Resolved Issues

##### **New MAC address range is now supported:**

A new range of MAC addresses has been accommodated for production of PlusConnect GatesAir ZXB units. This change has no user impact.

##### **The PlusConnect GatesAir ZXB now automatically re-initializes after loss of communication with the ARC Plus:**

If the communications link between the PlusConnect and the controlling ARC Plus system is broken for 3 minutes or more, the PlusConnect now automatically re-initializes to ensure proper operation on restoration of communication. Re-initialization has no effect on system configuration.