

Release Notes

PlusConnect GatesAir Z firmware version 1.12

Scope

This document describes the changes in PlusConnect GatesAir Flexiva firmware from version 1.9 to version 1.12.

Resolved Issues

The PlusConnect GatesAir Z now automatically re-initializes after loss of communication with the ARC Plus:

If the communications link between the PlusConnect and the controlling ARC Plus system is broken for 3 minutes or more, the PlusConnect now automatically re-initializes to ensure proper operation on restoral of communication. Re-initialization has no effect on system configuration.