



Product Update

Firmware Version 1.0.30 is now available for ARC Solo.

ARC Solo systems can now be upgraded with new features and capabilities. Changes from firmware version 1.0.29 to 1.0.30 are highlighted below. Detailed descriptions of these changes can be found in the Release Notes document included in the firmware download package.

Resolved Issues

- The “Clear all alarms” link on the Alarms page of the web interface now operates correctly regardless of the number of active alarms in the log.

To install the new firmware, visit www.burk.com/downloads, select the ARC Solo tab, and download Tech Bulletin - Uploading the ARC Solo Firmware. Follow these instructions to install the ARC Solo firmware folder titled 1.0.30.

For further information or for assistance with this upgrade, please contact Burk technical support at 978-486-3711 or by email at support@burk.com.