



## Product Update

Firmware Version 1.0.58 is now available for ARC Solo.

---

ARC Solo systems can now be upgraded with new features and capabilities. Changes from firmware version 1.0.56 to 1.0.58 are highlighted below. Detailed descriptions of these changes can be found in the Release Notes document included in the firmware download package.

### New Features and Enhancements

- The ARC Solo now supports Burk digital temperature sensors.

To install the new firmware, visit <https://www.burk.com/downloads>, select the ARC Solo support page, and download the Burk Firmware Loader Manual. Follow the instructions to install the new ARC Solo firmware.

For further information or for assistance with this upgrade, please contact Burk technical support at 978-486-3711 or by email at [support@burk.com](mailto:support@burk.com).