



Product Update

AutoPilot® Version 4.3.58 is now available for download.

AutoPilot software version 4.3.58 is now available. Changes from version 4.3.39 to version 4.3.58 are highlighted below. Detailed descriptions of these changes can be found in the Release Notes document included in the AutoPilot software download package.

New Features and Enhancements

- New docking panels have been added to the resources display.
- The Log4Net library has been updated.
- A new custom view template is now available.

Resolved Issues

- Network device logging capability has been restored.
- SNMP string objects now display string data correctly.
- Custom view validation has been enhanced.
- The dialog box warning that port 162 is in use is now self-dismissing.

To install the new software:

- 1) Visit www.burk.com/downloads and select the support page for AutoPilot.
- 2) Download the zip folder titled AutoPilot 4.3.58.
- 3) From this zip folder, extract and save files "Release Notes AutoPilot 4.3.58.pdf" and "AutoPilot_x64_4.3.58.exe".
- 4) Launch the AutoPilot_x64_4.3.58.exe file to install the new software version. It is not necessary to uninstall previous versions of the software before executing this file.

For further information or for assistance with this upgrade, please contact Burk Technology Technical Support at 978-486-3711 or by email at support@burk.com.