



## Product Update

***AutoPilot® Version 4.4.7.22 is now available for download.***

---

AutoPilot software version 4.4.7.22 is now available. Changes from version 4.4.7.21 to version 4.4.7.22 are highlighted below. Detailed descriptions of these changes can be found in the Release Notes document included in the AutoPilot software download package.

### **Resolved Issues**

- RTSP video controls now properly load in Custom Views.
- Saving Custom Views with web page objects no longer causes Arcadia to close.

To install the new software:

- 1) Visit [www.burk.com/downloads](http://www.burk.com/downloads) and select the support page for AutoPilot.
- 2) Download the zip folder titled AutoPilot 4.4.7.22.
- 3) From this zip folder, extract and save files "Release Notes AutoPilot 4.4.7.22.pdf" and "AutoPilot\_4.4.7.22.exe".
- 4) Launch the AutoPilot\_4.4.7.22.exe file to install the new software version. It is not necessary to uninstall previous versions of the software before executing this file.

For further information or for assistance with this upgrade, please contact Burk Technology Technical Support at 978-486-3711 or by email at [support@burk.com](mailto:support@burk.com).