



## Product Update

***Burk Firmware Loader Version 1.0.10 is now available for download.***

---

Burk Firmware Loader version 1.0.10 is now available for updating firmware in Burk Technology products. Changes from version 1.0.9 to 1.0.10 are highlighted below.

### **New Features and Enhancements**

- Dielectric Dual Switch Controller updates are now supported.

### **Affected Products**

Burk Firmware Loader version 1.0.10 or higher should be used to update firmware on the following Burk Technology products:

- ARC Plus
- ARC Solo
- Climate Guard
- Plus-X AC-8
- Plus-X GSC Adapter
- ARC Plus Touch
- Archer
- Plus-X 300
- Plus-X Dual IP-8 Adapter
- Plus-X ICRU
- ARC Plus SL
- Arcturus
- Plus-X 600
- Plus-X EM
- Plus-X IIU

To install the new software, visit [www.burk.com/downloads](http://www.burk.com/downloads), select the Burk Firmware Loader support page, and download and run the executable file [Burk Firmware Loader 1.0.10](#). Detailed release notes and the Burk Firmware Loader Manual can also be downloaded from this web page.

For further information or for assistance using the Burk Firmware Loader, please contact Burk Technology Technical Support at 978-486-3711 or by email at [support@burk.com](mailto:support@burk.com).