



Product Update

Firmware version 1.0.13 is now available for PlusConnect™ GatesAir Flexiva

PlusConnect GatesAir Flexiva units can now be upgraded with firmware version 1.0.13. Changes from firmware version 1.0.12 to 1.0.13 are highlighted below. Detailed descriptions of these changes can be found in the Release Notes document included in the firmware download package.

Resolved Issues

- Improved SNMP communication with transmitter

To install the new firmware, follow these steps:

- 1) Visit www.burk.com/downloads and select the support page for PlusConnect.
- 2) Download the firmware package for your PlusConnect™.
- 3) Download user instructions for your PlusConnect™ – Follow the instructions for updating firmware defined in the manual.

For further information or for assistance with this upgrade, please contact Burk technical support at 978-486-3711 or by email at support@burk.com.