



Release Notes

PlusConnect™ GatesAir ZXA firmware version 1.0.7

Scope

This document describes the changes in PlusConnect GatesAir ZXA firmware from version 1.0.6 to version 1.0.7.

Resolved Issues

New MAC address range is now supported:

A new range of MAC addresses has been accommodated for production of PlusConnect GatesAir ZXA units. This change has no user impact.

The PlusConnect GatesAir ZXA now automatically re-initializes after loss of communication with the ARC Plus:

If the communications link between the PlusConnect and the controlling ARC Plus system is broken for 3 minutes or more, the PlusConnect now automatically re-initializes to ensure proper operation on restoration of communication. Re-initialization has no effect on system configuration.