



## Product Update

Firmware Version 1.0.56 is now available for ARC Solo.

---

ARC Solo systems can now be upgraded with new features and capabilities. Changes from firmware version 1.0.47 to 1.0.56 are highlighted below. Detailed descriptions of these changes can be found in the Release Notes document included in the firmware download package.

### New Features and Enhancements

- Warp engine connections can now detect configuration changes.
- The date and time of the last configuration change are now available via SNMP.
- Arcadia authorization codes can now be entered manually from the ARC Solo web page.
- The number of user accounts has been increased.

### Resolved Issues

- Header text on the Jet Speech page has been updated.
- NTP server settings are now updated before synchronizing the time.
- The RSI now reads the meter label when reporting alarms.
- Clear alarm functions have been removed for users with observer access.
- Arcadia authorization codes now load consistently.

To install the new firmware, visit <https://www.burk.com/downloads>, select the ARC Solo support page, and download the Burk Firmware Loader Manual. Follow the instructions to install the new ARC Solo firmware.

For further information or for assistance with this upgrade, please contact Burk technical support at 978-486-3711 or by email at [support@burk.com](mailto:support@burk.com).