



## Product Update

Software Version 3.1.137 is now available for AutoLoad Plus.

---

AutoLoad Plus can now be upgraded with new features and capabilities. Changes from software version 3.1.135 to 3.1.137 are highlighted below. Detailed descriptions of these changes can be found in the Release Notes document included in the software download package.

### Resolved Issues

- GSC3000/VRC2500 configuration importer now properly handles all legacy decimal place options.

To install the new software, visit <https://www.burk.com/downloads>, select the AutoLoad Plus support page, download the software package and run the installer.

For further information or for assistance with this upgrade, please contact Burk technical support at 978-486-3711 or by email at [support@burk.com](mailto:support@burk.com).